

# National Athletic Equipment Reconditioners Association

BOB FAWLEY  
PRESIDENT

JASON SOARES  
VICE PRESIDENT

GREG HEIDER  
SECRETARY



www.naera.net

TONY BEAM  
EXECUTIVE DIRECTOR

DREW DIXON  
TREASURER

FRANK SCORDO  
MEMBER AT LARGE

ATHLETIC EQUIP.REPAIR  
MILWAUKEE, WI

ATHLETIC HELMET  
ALTO, TX

ATHLETIC HELMET SE  
TUSCUMBIA, AL

CAPITOL VARSITY SPORTS  
OXFORD, OH

CONTINENTAL ATH. SUPPLY  
GRIDLEY, CA

HARCO  
FT. COLLINS, CO

INTEGRITY SPORT SERVICE  
WADSWORTH, OH

MERCURY SPORTS  
EVANSVILLE, IN

PRO LINE, INC.  
MARIETTA, OH

RIDDELL /ALL AMERICAN  
North Ridgeville, OH

SCHUTT RECONDITIONING  
Salem, IL

SPORTSMAN'S RECOND  
JOHNSTOWN, PA

STADIUM SYSTEM  
CANAAN, CT

USA RECONDITIONING  
GARFIELD, NJ

XENITH  
DETROIT, MI

ATTENTION

August 29, 2024

It has been determined that the warning label placed on the exterior of football helmets reconditioned in 2024, could separate from the helmet under wet conditions. If during inspection of helmets in your inventory an exterior warning label is missing, this helmet should be taken out of play until the warning label is replaced.

Please contact your reconditioning representative for instruction.

NAERA recommends that during every football season or practice period, every helmet should be cleaned and inspected regularly by a school or organization staff member with knowledge of manufacturer recommendations.

Sincerely,

*Tony Beam*

Tony Beam, BA, E.S., CAA  
Executive Director, NAERA